Douglas County, KS Public Works: All Recorded Section Corner Reference Ties

Northing: Easting: Elevation: Coordinate Source:

N11P	Corner:	Section:	Township:	Range:	Surveyor: Stephan C. Tufte			
	CTR	21	13	19	Date Surveyed: 9/13/2019			
Corner Status Prior to Survey: Existent								
Monument Condition: Found								
All Measurements Are: Horizontal								
Original Description:								
Monument Description: 1/2" rebar, 0.1' above ground with steel post at north side								
Reference Tie 1:	60d spike in north N	face of 30" hee	dge tree, 2.38'	Reference Tie	5: drainage channel, 30' N			
Reference Tie 2:	60d spike in north face of 30" hedge tree, 19.18' W			Reference Tie	6: east-west fence line, 50' S			
Reference Tie 3:	60d spike in northeast face of 12" hackberry tree, 22.80' NW			Reference Tie	7:			
Reference Tie 4:	60d spike in north tree, 17.00' N	east face of 12	" hackberry	Reference Tie	8:			

N11P	Corner:	Section:	Township:	Range:	Surveyor: Brad Zilliox			
	CTR	21	13	19	Date Surveyed: 11/3/2015			
Corner Status Prior to Survey: Existent								
Monument Condition: Found								
All Measurements Are: Horizontal								
Original Description:								
Monument Description: 1/2" rebar found, T-post on north side for witness								
Reference Tie 1:	2.40' SE to 60d sp	ike found in 24	" tree	Reference Tie 5:				
Reference Tie 2:	19.15' W to 60d sp tree	oike found in no	orth face of 24"	Reference Tie 6:				
Reference Tie 3:	22.80' NW to 60	d spike found	in northeast	Reference Tie 7:				
	face 10" tree							
Reference Tie 4:	16.98' N to 60d sp	ike in east face	e 12" tree	Reference Tie 8:				

N11P	Corner:	Section:	Township:	Range:	Surveyor: Ron Shanks				
	CTR	21	13	19	Date Surveyed: 10/14/2015				
Corner Status Prior to Survey: Existent									
Monument Condition: Found									
All Measurements Are: Horizontal									
Original Description:									
Monument Description: 1/2" rebar									
Reference Tie 1:	T fence post 0.55'	N		Reference Tie 5:	spike in east face 12" hackberry 17.06' N				
Reference Tie 2:	spike in east face	twin 18" osage	orange 2.23'	Reference Tie 6:	flush with ground surface				
110.0.0.00	SSE		3.5gc =.=-5						
Reference Tie 3:	spike in north fa	ce 24" osage	orange 19.10'	Reference Tie 7:					
	•								
Reference Tie 4:	spike in northeast	face 12" hackb	erry 22.85' NW	Reference Tie 8:					